



位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-G-Pc1	入口大堂	地面層	0.00	0.00	0.23	0.02	127		0.00	0.03	0.37	0.02	151						
C-G-01	會客室	地面層	0.00	0.01	0.29	0.02	0		0.00	0.01	0.34	0.02	39						
C-G-02	傳達室	地面層	0.00	0.01	0.36	0.02	138		0.00	0.14	0.33	0.02	39						
C-G-02a	設備室	地面層	0.00	0.06	0.36	0.02	204		0.00	0.15	0.33	0.02	184						
C-B-02	儲存室	地庫層	0.12	0.01	0.40	0.03	138		0.12	0.00	0.34	0.02	52						
C-B-05	儲存室	地庫層	0.24	0.01	0.45	0.03	217		0.12	0.01	0.43	0.03	176						
C-B-06	儲存室	地庫層	0.24	0.01	0.45	0.03	310		0.09	0.01	0.30	0.02	159						


位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-B-07	儲存室	地庫層	0.68	0.00	0.40	0.02	244		0.09	0.01	0.30	0.02	59						
									0.10	0.00	0.36	0.02	34						
									0.01	0.01	0.35	0.02	19						
									0.11	0.00	0.36	0.02	36						
									0.06	0.01	0.36	0.02	52						
									0.08	0.01	0.36	0.02	79						
									0.08	0.02	0.36	0.02	82						

位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-2-01	高一乙	2	0.09	0.00	0.36	0.02	33		0.06	0.00	0.33	0.02	52						
									0.01	0.00	0.33	0.02	19						
									0.01	0.05	0.35	0.02	32						
									0.00	0.03	0.27	0.02	112						
									0.00	0.01	0.32	0.02	25						
									0.14	0.03	0.35	0.02	48						
C-3-06	高三丙	3	0.06	0.03	0.42	0.03	118		0.06	0.02	0.31	0.02	59						

位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-3-05	高三甲	3	0.09	0.00	0.44	0.03	462		0.17	0.00	0.35	0.02	103						
									0.16	0.01	0.36	0.02	18						
									0.18	0.01	0.35	0.02	26						
									0.19	0.01	0.35	0.02	37						
									0.00	0.06	0.35	0.02	105						
									0.18	0.00	0.35	0.02	79						
									0.04	0.01	0.35	0.02	65						

位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-5-01	電腦室	5	0.10	0.02	0.38	0.02	154		0.04	0.03	0.31	0.02	103						
									0.01	0.04	0.25	0.02	134						
									0.25	0.00	0.36	0.02	161						
									0.33	0.00	0.36	0.02	163						
									0.18	0.04	0.38	0.02	132						
									0.02	0.01	0.37	0.02	154						
									0.01	0.00	0.38	0.02	175						

位置資料							除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證			
C-6-03	辦公室	6	0.12	0.01	0.33	0.02	146		0.06	0.01	0.37	0.02	111						
									0.18	0.00	0.38	0.02	110						
									0.21	0.02	0.39	0.02	117						
									0.09	0.01	0.30	0.02	124						
									0.11	0.01	0.39	0.02	129						
									0.16	0.00	0.35	0.02	185						
									0.24	0.01	0.35	0.02	176						

位置資料									除甲醛前					除甲醛後					實證相片		
空間編號	空間名稱	樓層	NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣		NH <sub>3</sub>	HCHO	TVOC	C <sub>6</sub> H <sub>6</sub>	氯氣	除甲醛前數值	除甲醛後數值	實證					
C-7-03	音響室	7	0.10	0.00	0.38	0.02	202		0.08	0.03	0.32	0.02	165								
									0.01	0.01	0.31	0.02	140								
									0.12	0.00	0.36	0.02	109			